



SERVICE BULLETIN NZ SB132

To: Snorkel Service Dealers

Attention: Service Manager

Units affected: All MHP12J Trailers fitted with a Drawbar mounted Spare wheel.

MANDATORY MODIFICATION

This Bulletin is to inform you of a field modification that is required on all MHP12J Trailers that have a “drawbar mounted Spare wheel”.

The original position of the spare wheel mount is incorrect and it MUST be re-positioned or removed.

The original position of the spare wheel can have a negative effect on Stability when the Boom is rotated over the Drawbar and the maximum wind and manual forces are applied.

The Modification required is to move the crossmember rearwards by 200mm .

This will require a new crossmember be made from 50 x 50 x3RHS 606mm long, refer to the drawings attached.

The existing wheel mount can then be removed and welded to the new crossmember [the old crossmember can be left in place].

An alternative is to remove the Spare wheel mount from the existing crossmember and dispense with the Spare wheel altogether.

Contact the Snorkel Service Department if further information is required.



